

REMARKS

Claims 8-27 remain in this application.

Claims 20-24 and 27 have been withdrawn as directed to non-elected species.

In regard to the examiner's rejection of claims 8-19 and 25-26, based on the prior art reference to Stoecklein et al, the following is pointed out.

In the structure disclosed in the Stoecklein et al reference, the outlet throttle 64 is located between control chamber 58 and control valve 70, and is thus upstream of the control valve 70. The downstream part 66' of the outlet conduit 66 has a greater diameter than the throttles 64 and 86. Accordingly, outlet conduit 66 does not form an outlet throttle since it does not provide any throttling function for the outlet conduit.

Further, in the intermediary and the uppermost positions of valve element 76, the valve chamber 78 is connected to high pressure via bypass conduit 74 in order to close the injection nozzle faster. There is no communication from the control chamber 58 to the valve chamber 78 via the bypass conduit 74 since the pressure in the bypass conduit 74 is always higher than the pressure in the control chamber 58 when the valve member is in its intermediary and uppermost positions positions. Therefore, contrary to the reading of the Stoecklein et al reference as expressed by the examiner, in the structure of Stoecklein et al bypass conduit 74 is **not** a outlet conduit for the control chamber 58.

Thus the structure recited in claim 8 differs from the structure of Stoecklein et al in that:

- claim 8 recites that the outlet throttle 8 is located downstream of the control valve 6, between the control valve 6 and the low-pressure side 7;

Appl. No. 10/532,626
Amdt dated June 30, 2006
Reply to Office action of April 7, 2006

- claim 8 recites that the control chamber 2 communicates with the low-pressure side 7 via a second outlet conduit 16 having an outlet throttle 15 when the control valve 6 is in its third valve position.

Stoecklein et al does not teach, or in any way provide this structure.

Stated in different language, the Stoecklein et al reference lacks a second conduit (16) which communicates from the control chamber to the low pressure side. In Stoecklein et al the bypass conduit 74 does not lead from the control chamber, but rather leads from the chamber 44 which is part of the supply so that when valve 70 is in its uppermost position, bypass conduit 74 supplies fuel **into** the control chamber so that the injection nozzle closes faster.

While the examiner possibly might argue that in Stoecklein inlet conduit 62 leads to conduit 74 and thus 74 could act as a second outlet conduit, this position is refuted by the fact that high pressure in chamber 44 of Stoecklein et al will always keep fuel from flowing out of control chamber 58 through conduit 62. Thus, that there is no possibility of 74 acting as a communication from the control chamber 58 to low pressure side 66.

Further, there is no teaching of record which would in any way make the structure recited in claim 8 obvious to one skilled in the art.

Further, there is no teaching of record which would in any way make the structure recited in claim 8 obvious to one skilled in the art.

Since the present rejection of claim 8 has been shown to be inappropriate, and thus generic claim 8 is allowable, it is proper to reinstate non-elected claims 20-24 and 27, and allow them along with allowable claim 8, on which they ultimately depend.

Appl. No. 10/532,626
Amdt dated June 30, 2006
Reply to Office action of April 7, 2006

For the above reasons, entry of this amendment and allowance of all of the claims in this application are courteously solicited.

Respectfully submitted,

John F. Gonzales
~~JOHN F. GONZALES~~
~~REG. # 50,209~~
for Ronald E. Greigg
Attorney for Applicant(s)
Registration No. 31,517
Customer No. 02119

Date: June 30, 2006

GREIGG & GREIGG, P.L.L.C.
1423 Powhatan Street, Suite One
Alexandria, VA 22314

Tel. (703) 838-5500
Fax. (703) 838-5554

REG/SLS/ja

J:\Bosch\R304052\06-06-30, R304052, Amdt re OA of April 7, 06.wpd